



Change Log

December 1, 2016

Phottix Odin II Nikon

Firmware Versions:

v1.13 (Odin II Nikon Transmitter) and

v1.06 (Odin II Nikon Receiver)

Firmware Version v1.13 (Odin II Nikon Transmitter)

1. Fixes issue when Odin II triggers Strato II receiver, test button on transmitter will not function
2. Fixes issue when Odin II triggers Strato II receiver, the group on/off setting of the transmitter does not function properly

Firmware Version v1.06 (Odin II Nikon receiver)

1. Fix the issue with some camera effecting the brightness and accuracy of the SB-5000 flash

Phottix Odin II Nikon 觸發器

固件版本**V1.13** (發射器) **V1.06** (接收器)

更改纪录

2016年12月01日

一. ODIN II Nikon发射器V1.13版软件更改内容:

1. 搭配Strato II RX时, 按test键不能触发。
2. 搭配Strato II RX时, Odin II TX没有分组别。

二. ODIN II Nikon接收器V1.06版软件更改内容:

1. 修改了SB5000闪光灯在M档亮度不对的问题